

Mounting aid


MH-EXG-30



- Clamp for threaded pipe
- Suitable for all M30 sensors, including reduction factor 1
- Simple and quick exchange without readjustment
- 2 panel nuts included
- Free of paint wetting interfering substances
- Significantly reduced influence on the switching distance

Quick mounting bracket with dead stop

Dimensions



Technical Data

Release date: 2024-03-26 Date of issue: 2024-03-26 Filename: 70112559_eng.pdf

Ambient conditions	
Ambient temperature	-40 ... 90 °C (-40 ... 194 °F)
Mechanical specifications	
Length	L 36 mm thread length of sensor min. 34 mm
Diameter	sensor min. 29.73 mm sensor max. 30 mm
Material	brass, nickel-plated free of paint wetting interfering substances
Screwed connection	SW = 41 mm
Dimensions	M36 x 1.5 external thread
Tightening torque	36 Nm nuts 5 8 Nm nut 1
General information	
Note	Attention: Sensor shape dependent, it will be fixed up to 0.7 mm in back-flush position.

Refer to "General Notes Relating to Pepperl+Fuchs Product Information".

Pepperl+Fuchs Group
www.pepperl-fuchs.com


USA: +1 330 486 0001
fa-info@us.pepperl-fuchs.com

Germany: +49 621 776 1111
fa-info@de.pepperl-fuchs.com

Singapore: +65 6779 9091
fa-info@sg.pepperl-fuchs.com

 PEPPERL+FUCHS

Mounting



Mounting

1. Screw one hexagonal nut (5) onto the thread of sleeve (3).
2. Push sleeve (3) from the panel back side through an appropriate drill hole in the application.
3. Screw the second nut (5) from the panel front side onto the thread of sleeve (3).
4. Use both nuts (5) to adjust the horizontal position of the sensor.
5. Tighten the nuts (5) with the appropriate torque.
6. The fixation nut (1) turns on the retaining ring (2). Turn (1) until the three grooves on (1) and (3) are in line.
7. Insert the sensor from right-hand side through the inner hole of sleeve (3) until it touches the position stop (4).
8. Turn fixation nut (1) clockwise to fix the sensor. The use of tools is not necessary.

The sensor is fixed in position.